


Perception Surface Mounting Installation Guide


1. Measure and align the desired mounting location for the Perception surface mounted fixture and mark the location for the screw holes.

a. The mounting clip bar with the screw hole should be parallel to the desired path of the fixture.

b. Each mounting clip should be directly centered on the fixture.




2. Ensure the butterfly flange on the mounting clips are rotated so they are fully open. Fasten the mounting clips securely to the surface with screws.




3. Measure and mark the location on the surface where incoming power will be introduced to the fixture. Drill a hole in the surface for the power cable feed.


• IF YOUR PENDANT has an **ASYMMETRIC LENS** be sure to check which canopy will feed the power supply to properly orient your fixture.



4. While holding the fixture securely in place near the mounting surface, feed the power cable through the hole in the surface.



5. Press the fixture into the mounting clips so that the bar fits into the channel on top of the fixture.



6. With the fixture pressed into the clips, rotate each butterfly flange inward to lock the fixture in place. You may need to use an edge or pointed utensil to fully close the butterfly flanges under the fixture. It is important to ensure the butterfly flanges are fully closed to guarantee a secure hold for the fixture. Make all necessary electrical connections. Installation Complete.

